

Attorney Docket No. 381NP/50859 Filed: February 28, 2002 Sheet 1 of 19

FIG. 1



Attorney Docket No 381NP/50859 Filed: February 28, 2002 Sheet 2 of 19



Attorney Docket No. 381NP/50859 Filed. February 28, 2002 Sheet 3 of 19

FIG. 3






FIG. 4



Attorney Docket No 381NP/50859 Filed February 28, 2002 Sheet 4 of 19

FIG. 5




TORQUE TRANSMISSION ROUTE FROM 1st MOTOR

TORQUE TRANSMISSION ROUTE FROM 2nd MOTOR

Attorney Docket No. 381NP/50859 Filed February 28, 2002 Sheet 5 of 19

FIG. 6




POWER GENERATION ON 1st MOTOR BY PART OF ENGINE POWER

POWER GENERATION ON 2nd MOTOR BY PART OF ENGINE POWER

Attorney Docket No. 381NP/50859 Filed. February 28, 2002 Sheet 6 of 19

FIG. 7




TORQUE TRANSMISSION : _____

TORQUE TRANSMISSION ROUTE WHEN MOTOR : - RUNNING

Attorney Docket No. 381NP/50859 Filed: February 28, 2002 Sheet 7 of 19

FIG. 8




ENGINE RUNNING . ____

ACCELERATION ASSIST BY 1st MOTOR : -----

ACCELERATION ASSIST BY 2nd MOTOR : ----


Attorney Docket No 381NP/50859 Filed February 28, 2002 Sheet 8 of 19

FIG. 9



Attorney Docket No 381NP/50859 Filed February 28, 2002 Sheet 9 of 19

FIG. 10




 till that the thirt that the

Crowell & Moring LLP Customer Service No 23911

Attorney Docket No 381NP/50859 Filed: February 28, 2002 Sheet 10 of 19


FIG. 11




TORQUE TRANSMISSION : _____ : ____

TORQUE TRANSMISSION : _____ ROUTE OF 2nd MOTOR


Attorney Docket No. 381NP/50859 Filed: February 28, 2002 Sheet 11 of 19



Attorney Docket No. 381NP/50859 Filed February 28, 2002 Sheet 12 of 19




Attorney Docket No. 381NP/50859 Filed: February 28, 2002 Sheet 13 of 19



Attorney Docket No 381NP/50859 Filed: February 28, 2002 Sheet 14 of 19


FIG. 15




TORQUE TRANSMISSION ROUTE WHEN 3rd SPEED

TORQUE TRANSMISSION ROUTE WHEN 5th SPEED


Attorney Docket No. 381NP/50859 Filed. February 28, 2002 Sheet 15 of 19




Attorney Docket No. 381NP/50859 Filed. February 28, 2002 Sheet 16 of 19



Attorney Docket No 381NP/50859 Filed: February 28, 2002 Sheet 17 of 19




Attorney Docket No 381NP/50859 Filed: February 28, 2002 Sheet 18 of 19



Attorney Docket No. 381NP/50859 Filed: February 28, 2002 Sheet 19 of 19

FIG. 20



TORQUE TRANSMISSION ROUTE FROM 1st MOTOR: ————
TORQUE TRANSMISSION ROUTE FROM 2nd MOTOR:------